



J&A (International) Limited
THE GARMENT DECORATION SPECIALISTS

TECHNICAL DATASHEET

Visibility Transfers



www.ja-int.com | +44 (0)1790 752 757

J&A (International) Ltd. Insignia House, Vale Road, Spilsby, Lincolnshire PE23 5HE

Visibility Transfers



TECHNICAL DATASHEET

www.ja-int.com

APPLICATION

Temperature (°C): 150-180°C
Temperature (°F): 302-356°F
Time: 10 seconds
Pressure: Medium 42.7 - 56.9 psi / 2.9 - 3.9 bar / 3.0 - 4.0 kg/cm²
Carrier Release: Cold peel

LAUNDERING

Suitable for domestic wash up to 40°C
Tumble Dry - Medium
Iron - Medium, On Reverse
Do Not Dry-Clean
Do Not Bleach

HANDLING AND STORAGE

Store in a damp-free environment at a stable temperature of ~20°C
Keep away from direct sunlight
No personal protection equipment is required in handling and storage
Do not attempt to apply any transfer that has been removed from its carrier

COMPOSITION

Ink - Solvent based with glass bead coating
Adhesive - Polyester
Carrier - Polyester sheeting with glass-bead coating

HEALTH & SAFETY

This product is identified as Non-Hazardous to the end user
No PPE is required during application**

ENVIRONMENTAL / RECYCLING

Non-Recyclable
Vegan-Friendly: No

CERTIFICATION

Flame Retardant: EN ISO 11611 & EN ISO 11612

**Any fumes created by this transfer during application are harmless. However, modern garment materials can be coated and finished in many different ways; some of which may alter their application and health & safety requirements. We recommend thorough checking and testing of any garment material to determine the correct requirements before application.